

Cross reference list HALOTHERM lamps

Issue: 23.11.09

OSRAM HALOTHERM	EAN10	Radium ¹⁾ Ralotherm	Philips	Ushio	BLV	Victory Lighting	TOSHIBA, F
ITT 200/235-0170	4008321203472	ITT 200/235-0170			191705		
ITT 350/235-0170	4008321204219	ITT 350/235-0170			191505		
ITT 500/235-0170 K	4008321206701	ITT 500/235-0170 K	13169R		195405	64245023	JHS001
ITT 500/235-0170	4008321203519	ITT 500/235-0170					
ITT 500/235-0870	4008321206299	ITT 500/235-0870					
ITT 500/235-08X0	4008321203311	ITT 500/235-08X0			195489		
ITT 700/235-0170	4008321203533	ITT 700/235-0170					
ITT 1000/235-0170	4008321203557	ITT 1000/235-0170					
ITT 1000/235-01X0	4008321203199	ITT 1000/235-01X0	13195X	QIH240-1000/B	191029	64241027	J2JHS020
ITT 1000/235-08X0	4008321203434	ITT 1000/235-08X0	13195X/98	QIH240-1000/ZB	191089	64241053	2JHC008
ITT 1000/235-0826 S	4008321206275	ITT 1000/235-0826 S	13195Z/98	QIH 240-1000/ZD		64241052	2JHC105
ITT 1000/235-0826 S	4008321206275	ITT 1000/235-0826 S	13713Z/98	QIH240-1000/VZH	191093	64241052	2JHC015
RubyStar 1000/235-0023	4008321196743	RubyStar 1000/235-0023	13834Z/876 or 15007Z ²⁾	QIH240-1000R/VD3		64241332	2JHRQ018
ITT 1200/235-0826	4008321206374	ITT 1200/235-0826	14134Z/98	QIH230-1200/ZH		64231251	2JHC067
ITT 1200/235-0170	4008321916716	ITT 1200/235-0170					
RubyStar 1300/235-0070	4008321203618	RubyStar 1300/235-0070	15028R/876			64241372	
RubyStar 1500/235-0023	4008321196781	RubyStar 1500/235-0023	13123Z/876L or 15004Z ²⁾			64241571	2JHRQ019
RubyStar 1500/235-0026	4008321120557	RubyStar 1500/235-0026	13123Z/876 or 15010Z ²⁾	QIH240-1500R/D		64241571	
RubyStar 1500/235-0028	4008321196804	RubyStar 1500/235-0028					
ITT 1600/235-0826	4008321206398	ITT 1600/235-0826	14135Z/98	QIH230-1600/ZH		64141622	2JHC066
ITT 2000/235-0826 K/S	4008321206350	ITT 2000/235-0826 K/S	13168Z/98 13213Z/98F + 14103Z/98 ³⁾	QIH240-2000/VZD or VZH	194003	64242052	2JHC016
ITT 2000/235-0103 K	4008321203571	ITT 2000/235-0103 K					
ITT 2000/235-01Y0 K	4008321203595	ITT 2000/235-01Y0 K	13168X	QIH240-2000/VB			
RubyStar 2000/235-0023	4008321196620	RubyStar 2000/235-0023	15005Z ²⁾			64242070	EM-491
RubyStar 2000/235-0026	4008321289537	RubyStar 2000/235-0026	13934Z/876L or 15021Z ²⁾	QIH240-2000R/D			
RubyStar 2000/235-0028	4008321196675	RubyStar 2000/235-0028	15023Z ²⁾				
ITT 2200/235-0102	4008321203298	ITT 2200/235-0102			307048		2JHS234
ITP 2500/235V-0826 K/S	4008321252944						2JHC045
ITT 2500/400-0826	4008321206336	ITT 2500/400-0826	14143Z/98	QIH400-2500/ZH2		64242550	2JHC096
new ITT 2500/400-0826 M / S ⁴⁾	n/a		14106Z/98	QIH400-2500/ZH		64402550	2JHC036
ITT 3000/235-01Y0 K	4008321203458	ITT 3000/235-01Y0 K	13565X			64243024	2JHS060
ITT 3000/235-01Y0 Z/K	4008321206725	ITT 3000/235-01Y0 Z/K					
ITT 3000/235-0102 K	4008321387127		13565V	QIH240-3000/VC			JHS006
ITT 3000/400-0826	4008321206312	ITT 3000/400-0826	14144Z/98	QIH400-3000/ZH2		64243055	2JHC097
new ITT 3000/400-0826 M / S ⁴⁾	n/a		14111Z/98	QIH400-3000/ZH		64403052	2JHC037

¹⁾ Radium order code in the past

³⁾ Philips burning position p15

²⁾ Philips HeLeN (gold coated)

⁴⁾ in the pipeline